


Supply Module Relay Failure – Water Intrusion on BBCV/Vision Tech Tip #18-0423



Water Intrusion – Supply Module Relay

We have seen instances where there will be a MIL or CEL and checking has found that the code thrown is for accelerator pedal voltage or erratic data. Some of the codes have been 1239, 1241, 1242, 1515. After diagnosing the issue, it was discovered that the "Supply Module Relay" had failed and once removed corrosion can be seen in the holder (FIGURE #1).

Upon further investigation we learned that there is a rubber grommet located in the center of the firewall with a loomed harness passing through it (FIGURES #2 & #3). The grommet is located below the 2 bulkhead connectors (FIGURE #4) and can be located inside the unit once the PDU cover is removed. Cleaning the connector and relay terminals once the grommet is sealed may allow the MIL/CEL to be cleared, but in some instances the module relay may need to be replaced.










FIGURE #1



FIGURE #2



FIGURE #3









FIGURE #4

SUPPLY MODULE RELAY

PART # 01746387







CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232

Dave Schaub

Albany: 866-8671100

Ben Reiling

Middletown: 845-609-7070

Marc Matwijec

Warranty: 800-962-5768

Morgan Jenkins **Customer Service Representatives**

Eastern Region:

Gary Bigness 845-500-3707

Central Region:

JJ Richmond 315-559-3999

Western Region:

Mike Panzica 716-908-3186 **PARTS**

Director of Parts

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com





