

# Tech Tip



*From your friends at New York Bus Sales*

## Product Affected-Early Production All American “D3” Forward Engine

- Complaint -** The heater hose running to the right rear corner of the engine is rubbing on the engine hood – causing the heat wrap to wear through and if not caught in time the hose to wear into the cords.
- Cause -** Routing – The hose is improperly routed and needs to be rerouted so it does not contact the engine hood and is further away from the exhaust manifold.
- Correction -** In Figure #1 you can see current routing and how the valve assembly goes over the top of the exhaust manifold. Figure #2 shows the marks left in the engine hood insulation from this routing. You first need to let the engine cool and then drain off coolant so that it is below the level of the engine block. Next remove the hose from the fitting. Remove the fitting from the valve and replace with fitting #00103628 which is a 90\* fitting. Tighten the valve assembly in the head turning it 90\* to point towards the rear of the doghouse as in Figure #3. Using thread sealant, install #00103628 in the valve and tighten bringing to the 4 o'clock position as in Figure #3. If there is not enough hose or it has “wear” damage it should be replaced and then the insulation cover replaced - #00118668




FIGURE #1




FIGURE #2




FIGURE #3

**IMPORTANT INFORMATION**  
**FITTING PART #00103628**  
**HOSE INSULATION PART #00118668**



**Contact Our Service Department With Any Questions**

**CHITTENANGO** – phone 800-962-5768 or

Daryl Wallace : [dwallace@newyorkbussales.com](mailto:dwallace@newyorkbussales.com)

Brian Lamaitis : [blamaitis@newyorkbussales.com](mailto:blamaitis@newyorkbussales.com)

**ROCHESTER** – phone 800-463-3232 or

Gary Chichester: [gchichester@newyorkbussales.com](mailto:gchichester@newyorkbussales.com)

**ALBANY** – phone 866-867-1100 or

Ben Reiling: [breiling@newyorkbussales.com](mailto:breiling@newyorkbussales.com)

Steve Searles: [ssearles@newyorkbussales.com](mailto:ssearles@newyorkbussales.com)

**WARRANTY** – 800-962-5768 ext 237

Morgan Jenkins: [mjenkins@newyorkbussales.com](mailto:mjenkins@newyorkbussales.com)

ALL of our Tech Tips can be found on the New York Bus Sales website at

<http://www.newyorkbussales.com/pages/bulletins.cfm>

Or at the New York Head Mechanic website at

<http://www.nyhma.org/viewforum.php?f=2&start=0>