
School Buses Services Parts



FORD/ROUSH Air Compressor Drive Pulley PARTS UPDATE #16-0407PP





CHANGE IN AIR COMPRESSOR DRIVE PULLEY

Roush made a running change in the "dual" pulley used to drive the air compressor on units equipped with air brakes.

Figures #1 & #2 on the following page show the original pulley and you can see how the mounting washer is deep into the pulley.

Figures #3 & #4 show the new pulley and you can see they have doubled the bearing surface by adding another bearing in the pulley and provided a longer mounting bolt for the decreased depth.

New York Bus Sales will be using the updated pulley from this point forward.

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website









FIGURE #1




FIGURE #2



FIGURE #3




FIGURE #4

OLD PART NEW PART #10023176 # S-P11BB-PULYKIT-AA

ALL of our Service Updates can be found on the New York Bus Sales website Or at the New York Head Mechanic website







CONTACT OUR PARTS DEPARTMENT WITH ANY QUESTIONS

Director of Parts

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

John Green

jgreen@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

Ryan Krolak

rkrolak@newyorkbussales.com

PLEASE NOTE – THE BEARING WHILE BEING AN A/C COMPRESSOR CLUTCH BEARING (NSK #30BD40DF2) IS NOT RECOMMENDED TO BE CHANGED BY ROUSH AND WILL VOID ANY FUTURE FAILURES ON THE COMPONENT



NSK BEARING #30BD40DF2

ALL of our Service Updates can be found on the New York Bus Sales website
Or at the New York Head Mechanic website





