



Tech Tip – 15-0209-1

Product Affected – GM Type “A” Gas Fuel Fill Issues

Complaint: Drivers are complaining that units are slow to fill with gas.

Cause: After inspecting several units and verifying there were no fuel line restrictions, we looked to GM for assistance. The “EVAP VENT VALVE” was found to be shorted and required replacement.

Correction: Replace solenoid #20941985

**THANKS TO MIKE MATTLE AND SPENCERPORT CENTRAL SCHOOL
FOR WORKING WITH US TO ADDRESS THE ISSUE**

For more information contact our nearest Service Department

Chittenango: 315-687-3969 or 1-800-962-5768	Daryl Wallace or Brian Lamaitis
Rochester: 585-424-3320 or 1-800-463-3232	Gary Chichester or Dave Schaub
Ravena: 518-756-1111 or 1-866-867-1111	Ben Reiling

Customer Service Representatives

Eastern Region	Gary Bigness 845-500-3707
Central Region	JJ Richmond 315-559-3999
Western Region	Mike Panzica 716-908-3186