

From your friends at New York Bus Sales

Product Affected-Diesel Engines with New Emissions

Complaint - The exhaust manifold seems to be leaking as there is a black "soot" trail

forming but there does not seem to be a leak-

Cause - With the new emissions not producing "soot" as in the past, when the engines

are cold the metals may contract which may allow slight gaps (Especially in units with multiple piece exhaust manifolds) where, when the engine is started the exhaust leaks out and causes these streaks. Once the engines warm these

voids in the parts are not seen due to metal expansion.

Correction - Make sure that you are checking for exhaust leaks with the engine at

operating temperature – This way you know that the metals have expanded to their full size. Even with the slightest contraction and expansion when sealing these, the manifolds may again leak when cold and then seal when at

operating temperature.



Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : <u>dwallace@newyorkbussales.com</u> Brian Lamaitis : <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY - phone 866-867-1100 or

Ben Reiling: <u>breiling@newyorkbussales.com</u>
Steve Searles: <u>ssearles@newyorkbussales.com</u>

eve Scaries. <u>sscaries@newyorkbussales.cor</u>

WARRANTY - 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at http://www.newyorkbussales.com/pages/bulletins.cfm
Or at the New York Head Mechanic website at http://www.nyhma.org/viewforum.php?f=2&start=0