

From your friends at New York Bus Sales

Product Affected-TYPE A/GM GAS CHASSIS

Complaint - We go to start the bus – turn the key and there is nothing! Recycling the key

and it may power up or it may take 2 tries!

Cause - With the new engine electronics there is a "Hi-Speed" ECM which requires

more voltage at start up than in previous years and with the body requiring power and the possibility of added switches left on at shutdown the single 600 CCA better this is the ball and the state of the state of

CCA battery which is standard may not have the necessary reserve power.

Correction - First – As always make sure that drivers are shutting down ALL electrical

switches when they shut the unit down.

Second-Replace the battery with a higher CCA battery which will have the added reserve necessary or better yet add an extra battery in series to the unit

which will assure there will be no issues!

As Always KEPP THIS IN MIND WHEN SPEC'ing NEW UNITS!!!



THANKS TO MARK KOZINA FROM UNION ENDICOTT CENTRAL SCHOOL FOR POINTING THIS OUT!

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : <u>dwallace@newyorkbussales.com</u> Brian Lamaitis : <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or Ben Reiling: breiling@newyorkbussales.com

Steve Searles: ssearles@newyorkbussales.com

WARRANTY - 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at http://www.newyorkbussales.com/pages/bulletins.cfm
Or at the New York Head Mechanic website at http://www.nyhma.org/viewforum.php?f=2&start=0