


Tech Tip

FROM YOUR FRIENDS AT
NEW YORK BUS SALES!



Cummins “Unique Operating Characteristics”

- Complaint –** Unit was idling and then all of a sudden the RPMs rose
- Cause –** The unit has idled for an extended period and the unit is warming up to help prevent the buildup of condensation.
- Correction –** Minimize Idle Time is basically the way to correct this happening

PLEASE SEE THE ATTACHED!



ALL of our Tech Tips can be found on the New York Bus Sales website at
<http://www.newyorkbussales.com/pages/bulletins.cfm>
Or at the New York Head Mechanic website at
<http://www.nyhma.org/viewforum.php?f=2&start=0>