

Stainless Steel Braided From Compressor to Air Dryer

Complaint - We found that the stainless steel braided line from the compressor to the air

dryer had a spot where the braids are broken and the rubber hose is starting to

"bulge" through, please see Figures #1, #2 & #3.

Cause – We believe after reviewing several units that the cause maybe associated with the

plastic tag which is on the hose as identification Please See Figure #4. We suspect that road chemicals trapped beneath the tag along with the varying change in temperature as the units cycles air compressor cycles may be what is leading to

the issue.

Correction – Remove the tag from the line





FIGURE #1 FIGURE #2





FIGURE #3 FIGURE #4

THANK YOU TO HARRY &
JEREMY FROM DUANESBURG
CENTRAL SCHOOL FOR
BRINGING THIS TO OUR
ATTENTION!!!



Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or Daryl Wallace: <u>dwallace@newyorkbussales.com</u> Brian Lamaitis: <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or Ben Reiling: breiling@newyorkbussales.com

WARRANTY – 800-962-5768 ext 237 Morgan Jenkins: <u>mjenkins@newyorkbussales.com</u>

Or Your Customer Support Representative

West

Michael Panzica — <u>mpanzica@newyorkbussales.com</u> Cell 716-908-3186

Central

Jeremie "JJ" Richmond -

jjrichmond@newyorkbussales.com

Cell 315-559-3999

East

Gary Bigness – <u>gbigness@newyorkbussales.com</u> Cell 845-500-3707

ALL of our Tech Tips can be found on the New York Bus Sales website at http://www.newyorkbussales.com/pages/bulletins.cfm
Or at the New York Head Mechanic website at http://www.nyhma.org/viewforum.php?f=2&start=0