

T3FE Steering Column Boot Clamp

Complaint – Steering seems to have a slight "catch" in it when turning from lock to lock

Cause – The "boots" on the lower section of the shaft have a clamp installed which does not allow the steering shaft to turn smoothly and the boot in some cases will rip as the clamp is holding it too tight to the shaft.

Correction – Removing the clamp (Shown with the arrows in Figures #1 & #2) will allow the shaft to move unrestricted and without any "catching"






Figure #1 Figure #2

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or Daryl Wallace: <u>dwallace@newyorkbussales.com</u> Brian Lamaitis: <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or Gary Chichester: <u>gchichester@newyorkbussales.com</u>

ALBANY – phone 866-867-1100 or Ben Reiling: <u>breiling@newyorkbussales.com</u>

WARRANTY – 800-962-5768 ext 237 Morgan Jenkins: <u>mjenkins@newyorkbussales.com</u>

Or Your Customer Support Representative West

Michael Panzica – <u>mpanzica@newyorkbussales.com</u>

Cell 716-908-3186

Central

Jeremie "JJ" Richmond –

jjrichmond@newyorkbussales.com

Cell 315-559-3999

East

Gary Bigness – <u>gbigness@newyorkbussales.com</u> Cell 845-500-3707

