

## "Weep" hole in GM Propane Muffler from AutoJet

Complaint – There is what appears to be a "welded" weep hole in the front "cover" of the muffler – Please see photos #1 & #2

Cause – During production, the weep hole was mis-drilled in this location. To address this they welded the holes and re-drilled the holes on the case towards the bottom (Figure #3)

**Correction –** No Correction Needed





FIGURE #1 FIGURE #2

PLEASE NOTE – With the weather conditions being as cold as they have been over the past couple of weeks, you may note what appears to be an excessive amount of water coming from the weep hole. This is normal in cold weather as there is much more condensation!



FIGURE #3



## Contact Our Service Department With Any Questions

**CHITTENANGO** – phone 800-962-5768 or Daryl Wallace: <u>dwallace@newyorkbussales.com</u>

Daryl Wallace: <u>dwallace@newyorkbussales.com</u> Brian Lamaitis: <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or Ben Reiling: <u>breiling@newyorkbussales.com</u>

WARRANTY – 800-962-5768 ext 237 Morgan Jenkins: mjenkins@newyorkbussales.com

## Or Your Customer Support Representative

West

Michael Panzica – <u>mpanzica@newyorkbussales.com</u>

Cell 716-908-3186

Central

Jeremie "JJ" Richmond –

jjrichmond@newyorkbussales.com

Cell 315-559-3999

East

Gary Bigness – <u>gbigness@newyorkbussales.com</u> Cell 845-500-3707

ALL of our Tech Tips can be found on the New York Bus Sales website at <a href="http://www.newyorkbussales.com/pages/bulletins.cfm">http://www.newyorkbussales.com/pages/bulletins.cfm</a>
Or at the New York Head Mechanic website at <a href="http://www.nyhma.org/viewforum.php?f=2&start=0">http://www.nyhma.org/viewforum.php?f=2&start=0</a>