

## **Microbird MBII Entrance Door**

Complaint - Our "Single Rear Wheel" Microbird Model "MBII" has noise

coming from the entrance door area.

Cause – The LEFT HAND door panel "Sweep"

Correction – Microbird has released the attached "modification" to address the

issue.

**NEW YORK BUS SALES** 

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or Daryl Wallace: dwallace@newyorkbussales.com

Brian Lamaitis: <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or Ben Reiling: <u>breiling@newyorkbussales.com</u>

WARRANTY – 800-962-5768 ext 237

Morgan Jenkins: <u>mjenkins@newyorkbussales.com</u>

Or Your Customer Support Representative

West

Michael Panzica – mpanzica@newyorkbussales.com

Cell 716-908-3186

Central

Jeremie "JJ" Richmond -

jjrichmond@newyorkbussales.com

Cell 315-559-3999

East

Gary Bigness – gbigness@newyorkbussales.com

Cell 845-500-3707

ALL of our Tech Tips can be found on the New York Bus Sales website at <a href="http://www.newyorkbussales.com/pages/bulletins.cfm">http://www.newyorkbussales.com/pages/bulletins.cfm</a>
Or at the New York Head Mechanic website at <a href="http://www.nyhma.org/viewforum.php?f=2&start=0">http://www.nyhma.org/viewforum.php?f=2&start=0</a>

Body Tech Tip #14-0929



## DOOR WHISTLE ON MICRO BIRD MBII MODEL BUSES

Customers have been reporting that on some MBII they own, the double entrance doors are whistling on the road. We have not taken this lightly and have done some changes to our design to avoid this.

The following things have been changed in production and may be done to stop this unpleasant noise.

- We started by inverting the door seals.
- We installed rubber sweeper behind the door stoppers which, at first, was full length.
- The design of that part has been revised and now has a new shape. If you have sweepers on your bus, you may cut it as per the drawing below.



Body Tech Tip #14-0929 Page 2