

GM Type "A" Gas Fuel Fill Issues

Complaint – Drivers are complaining that units are slow to fill with gas.

shorted and required replacement.

Cause – Whereas the first thought always is that the body up fitter has run the fuel fill hose from the body to the gas tank and restricted the flow by narrowing where the hose is routed. After inspecting several units and verifying that there were no restrictions, we looked to GM for assistance. What was found was that the "EVAP VENT VALVE" had

Correction – Replace solenoid #20941985 –



THANKS TO MIKE MATTLE AND SPENCERPORT CENTRAL SCHOOL FOR WORKING WITH US TO ADDRESS THE ISSUE Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or Daryl Wallace: <u>dwallace@newyorkbussales.com</u> Brian Lamaitis: <u>blamaitis@newyorkbussales.com</u>

ROCHESTER – phone 800-463-3232 or Gary Chichester: <u>gchichester@newyorkbussales.com</u>

ALBANY – phone 866-867-1100 or Ben Reiling: <u>breiling@newyorkbussales.com</u>

WARRANTY – 800-962-5768 ext 237 Morgan Jenkins: mjenkins@newyorkbussales.com

Or Your Customer Support Representative

West

Michael Panzica — <u>mpanzica@newyorkbussales.com</u> Cell 716-908-3186

Central

Jeremie "JJ" Richmond — <u>jjrichmond@newyorkbussales.com</u> Cell 315-559-3999

East

Gary Bigness – <u>gbigness@newyorkbussales.com</u> Cell 845-500-3707 ALL of our Tech Tips can be found on the New York Bus Sales website at http://www.newyorkbussales.com/pages/bulletins.cfm
Or at the New York Head Mechanic website at http://www.nyhma.org/viewforum.php?f=2&start=0