



IMMI Seat Belt Retractor Issue

Service Update #26-0723



3-Point Seat Belt Retractor Not Working

Recently we had a retractor that would not retract and the assumption was that there was an issue and the retractor would need to be replaced.

After further diagnosis, we found that the retractor was fine, and the issue was that the “clip” installed on the retractor when the seat was assembled was not removed and was not allowing the belt to retract. FIGURES #1, #2 & #3 show the clip installed on the retractor.

Removing the clip will allow the retractor to work as intended.

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)



FIGURE #1



FIGURE #2




FIGURE #3

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Road Mechanic website](#)

CONTACT US FOR SERVICE or QUESTIONS

Director of Service

Matt Woodman

mwoodman@newyorkbussales.com

Chittenango: 800-962-5768

Morgan Jenkins

mjenkins@newyorkbussales.com

Brian Goodfellow

bgoodfellow@newyorkbussales.com

Bob Reith

breith@newyorkbussales.com

Phil Tucker

ptucker@newyorkbussales.com

Albany: 866-867-1100

Ross Phipps

rphipps@newyorkbussales.com

Customer Support

Ben Reiling

breiling@newyorkbussales.com

Batavia: 800-463-3232

Matt Dargusch

mdargusch@newyorkbussales.com

Eric Bosley

ebosley@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Road Mechanic website](#)

