



Microbird Warning Lights

Parts Update #17-05



Lights Replaced Under Warranty/Bulbs are Available Separately

The standard halogen warning lights on the Microbird product have a changeable bulb (Figure #1). When installed at the factory, the bulb is coated with caulk to reduce water infiltration (Figure #2). Often times removing the caulk is difficult. Therefore, when covered under their 3 year/36,000-mile warranty, Microbird covers the light assembly. When replacing under warranty, you will see the new light is shipped with no caulk (Figure #3). It is the discretion of the operator; however, it's recommended that some sort of sealant or caulk be used around the bulb to aid in water infiltration.

PART #27E0068 Amber Light

PART #27E0069 Red Light

PART #BP1255H3 Replacement Bulb

**THANK YOU TO DAN ELDERBROOM AND THE GANG AT
LIVERPOOL CENTRAL SCHOOLS FOR POINTING THIS OUT!**

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)



Figure #1



Figure #2



Figure #3

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT OUR PARTS DEPARTMENT WITH ANY QUESTIONS

Director of Parts

Jim Hogan

jhogan@newyorkbussales.com

607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

