Ford/Roush Starter Connections

Tech Tip #18-0309-RP



Starter Connections Require Maintenance

We have found several units where corrosion has basically eaten the ends off of the cables (FIGURE #1). In some instances, this was caught during normal PM maintenance, but on more than one occasion a unit was down because of this. The issue is that not only are the ends deteriorating, but the cable itself is compromised and needs replacing as well (FIGURE #2 & 4).

Blue Bird coats these connections with "Glyptal 1201" which is a specially formulated red enamel sealer used to protect electrical connections.

During PM inspections, these connections should be checked and recoated with a similar product. It is also recommended during the annual inspection to actually remove the cable to more closely inspect it and clean and recoat after reassembly.

Figure #5 shows the cable locations on the starter.












FIGURE #1



FIGURE #3



FIGURE #4










FIGURE #5







CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232

Dave Schaub

Albany: 866-867-1100

Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins
Customer Service
Representatives

Eastern Region:

Gary Bigness 845-500-3707

Central Region:

JJ Richmond 315-559-3999

Western Region:

Mike Panzica 716-908-3186 **PARTS**

Director of Parts

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com





