

AMETEK DASH CLUSTER

Parts Update #17-0928



Dash Cluster Navigation Button Covers

It's been brought to our attention that customers with the new Ametek dashes have seen the rubber covers for navigation buttons (#11 in Figure #1) come free and get lost, which require being replaced. Customers believe they may have "popped" out when the dash was being cleaned. Figure #2 shows what the dash looks like with the cover missing.







PLEASE NOTE – THIS IS BASICALLY A COVER TO PREVENT DUST/DIRT FROM GETTING INTO THE DASH. HAVING IT NOT THERE DOES NOT IMPEDE THE OPERATION OF THE DASH.

The actual button "humps" are not centered on the rubber strip, so attention needs to be paid when reinstalling. (Figure #3). The cover is held in place by design. The cover is designed to go over the buttons and extend through the plexiglass cover of the cluster (Figure #4).

REPLACEMENT COVER
PART # LIST PRICE
10056715 \$3.01










Figure #1



Figure #2

ALL of our Service Updates can be found on the New York Bus Sales website Or at the New York Head Mechanic website







3





Figure #3

Figure #4







CONTACT OUR PARTS DEPARTMENT WITH ANY QUESTIONS

Director of Parts

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com





