



Microbird Ford & GM Wheel Chair SERVICE NOTICE #17-1006



Lift and Interlock Power with Brake Depressed

Micro Bird recently sent out “Engineering Change Notice #17-0013” concerning a safety point on the lift door interlock system.

Please note that since September 2013, Micro Bird buses have an additional safety feature; when a unit is operating and the lift door is open, if there is someone in the driver's seat and the brake pedal is depressed (as if attempting to move the vehicle), the power supply to the lift is interrupted but the lock remains activated so that the vehicle cannot be moved. This additional feature ensures that the unit cannot be moved and warns the lift operator that someone is in the driver's area.

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768
Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232
Dave Schaub

Albany: 866-867-1100
Ben Reiling

Warranty: 800-962-5768
Morgan Jenkins

**Customer Service
Representatives**

Eastern Region:
Gary Bigness
845-500-3707

Central Region:
Josh Coon
315-263-0765

Western Region:
Mike Panzica
716-908-3186

PARTS

Director of Parts
Jim Hogan
jhogan@newyorkbussales.com
607-227-5794

Chittenango: 800-962-5768
Gari McQuade
gmcquade@newyorkbussales.com
Bill Cox
bcoc@newyorkbussales.com
John Lewin
jlewin@newyorkbussales.com
Dave Grant
dgrant@newyorkbussales.com

Albany: 866-867-1100
Sean Conway
sconway@newyorkbussales.com
Pat Murphy
pmurphy@newyorkbussales.com

Rochester: 800-463-3232
Dave Cook
dcook@newyorkbussales.com
Steve Hibbard
shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

