Microbird G5 Whistling Noise Tech Tip #17-0304





"Wind" Whistling Noise While Driving G5 Microbird

It has come to our attention that there is a "whistling" noise that drivers hear on the Microbird G5. Iroquois Central School realized that the noise was coming from the driver's rearview mirror. They found that the "shell" of the mirror where the head mounts along the 2 seams horizontally in the mirror head (Figure #1) was causing the issue. They verified this by running a bead of caulk along those seams and the "whistling" was no longer there. New York Bus Sales contacted Rosco who said they had heard of similar issues on another product. Their recommendation was to lower the mirror head on the stalk by ½" as that also had resolved the issue.

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website









Figure #1

THANK YOU TO JEFF AND THE FOLKS AT **IROQUOIS CENTRAL SCHOOL FOR POINTING THIS** OUT.

ALL of our Service Updates can be found on the New York Bus Sales website Or at the New York Head Mechanic website







CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232 Dave Schaub Albany: 866-867-1100 Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins
Customer Service
Representatives

Eastern Region:

Gary Bigness 845-500-3707

Central Region:

JJ Richmond 315-559-3999

Western Region:

Mike Panzica 716-908-3186

PARTS

Director of Parts

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website





