

# Cummins Oil Leak Engine Tech Tip #17-0213



## Oil Leak is Easily Repaired on Air Compressor

Oil leaks have been found in the area of the air compressor. At the bottom of the compressor and after cleaning the engine, a "soft plug" was located. We have seen oil seep from around the plug as well as the plug actually "corroding" and causing a leak.

That plug is not shown in any of the Cummins parts documentation, but our New York Bus Sales Parts Department researched and found there actually was a part number **4089675** for the plug. This plug eliminates the timely and costly need to replace the complete compressor. Figure #1 shows plug in the bottom of the compressor.

Part number 4089675 is available through the New York Bus Sales Parts Department.

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website










Figure #1

ALL of our Service Updates can be found on the New York Bus Sales website Or at the New York Head Mechanic website







## CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

#### **SERVICE**

**Chittenango:** 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232 Dave Schaub Albany: 866-867-1100 Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins
Customer Service
Representatives

## **Eastern Region:**

Gary Bigness 845-500-3707

### **Central Region:**

JJ Richmond 315-559-3999

#### **Western Region:**

Mike Panzica 716-908-3186

#### **PARTS**

#### **Director of Parts**

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

**Chittenango:** 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

**Dave Grant** 

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

John Green

jgreen@newyorkbussales.com

Rochester: 800-463-3232

**Dave Cook** 

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website





