BLUE BIRD SEAT BACKS

Tech Tip #16-1107



Seat Back Wood "Staple Board"

Recently we learned of an issue customers were seeing when trying to replace the seat back covers on their units. When removing the cover, the wood which is there to staple the cover to, comes loose from the seat frame making changing the cover more difficult. This wooden strip (Figure #1) is actually stapled to the seat frame through the seat back pan (Figure #2). Figure #3 shows how the wooden strip can pull away from the seat pan. We have worked with Blue Bird and found that if the strip is loose or not attached to the seat pan that a ½"X#6 "Burr-less" head wood screws can be used to attach the wooden strip. We use a 5/32nd drill bit and pre-drill one hole each where the staples were (Figure #4).

NOTE: PLEASE ENSURE THAT THE POINT OF THE SCREW DOES NOT PROTRUDE THROUGH THE WOOD

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website









Figure #1




Figure #2




Figure #3



Figure #4

THANKS TO RYAN FROM LAKESHORE CENTRAL SCHOOL FOR POINTING THIS **OUT TO US!**

ALL of our Service Updates can be found on the New York Bus Sales website Or at the New York Head Mechanic website







CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232 Dave Schaub Albany: 866-867-1100 Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins
Customer Service
Representatives

Eastern Region:

Gary Bigness 845-500-3707

Central Region:

JJ Richmond 315-559-3999

Western Region:

Mike Panzica 716-908-3186

PARTS

Director of Parts

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

John Green

jgreen@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website





