

## Roush Propane Y-Pipe Heat Sleeves Tech Tip #16-0924PP



## **HEAT SLEEVES ARE NO LONGER REQUIRED**

NYSDOT and Blue Bird has in the past required that the Roush Propane Exhaust Y-Pipe Heat Sleeves be present. However, due to harsh Northeast road conditions, we have seen these sleeves need replacement due to deterioration.

Blue Bird engineering has determined through continued testing that the heat "sleeves" which were initially installed on the Y-pipes of the Roush propane product are NOT required. NYSDOT has been informed and is in agreement that units will not fail due to missing or damaged sleeves. Therefore, if the sleeves are damaged or missing, their replacement is NOT required.

Attached is the letter from Blue Bird stating these are no longer required.

Please Reference Tech Tip #13-0603-1RPREVA

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website









September 21, 2016

Subject: Gen 3 Propane Vision Exhaust Y-Pipe Heat Sleeves

To whom it may concern,

This memo is to address the Exhaust Y-Pipe Heat Sleeves on the Gen 3 Propane Vision Product. These heat sleeves were installed to mitigate a severe duty cycle condition that drives the transmission oil temperature above a temperature goal. This test was conducted on an 11% grade at full GVWR of 33,000 lbs. and the temperatures peaked just over the limit temperature.

It is therefore the recommendation of Blue Bird Engineering that the sleeves are not required in most operating conditions such as in northern dimates and common road grade cycles. Blue Bird Engineering is now in the process of designing heat shields for service to address these extreme conditions; however the vast majority of our customers do not need this additional insulation. If you have any questions about the necessity of using this additional insulation in your applications please contact your Field Service Engineer.

Regards,

Paul Barrs

Manager, Engineering Support & Service Blue Bird Corporation

## CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

**SERVICE** 

**Chittenango:** 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463 3232

**Dave Schaub** 

Albany: 866-867-1100

Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins
Customer Service
Representatives

**Eastern Region:** 

Gary Bigness 845-500-3707

**Central Region:** 

JJ Richmond 315-559-3999

**Western Region:** 

Mike Panzica 716-908-3186 **PARTS** 

Jim Hogan

jhogan@newyorkbussales.com

607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

**Dave Grant** 

dgrant@newyorkbussales.com

**Albany:** 866-867-1100

Sean Conway

sconway@newyorkbussales.com

John Green

jgreen@newyorkbussales.com

Rochester: 800-463-3232

**Dave Cook** 

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website





