



CUMMINS IN-LINE DIAGNOSTIC ADAPTER

PARTS UPDATE #16-0415



NEW CUMMINS ADAPTER REQUIRED

Due to EPA regulations recently implemented, a change in the diagnostic connection has been made requiring a different adapter used with the In-Line 6 Data Link. This will effect most new large, type C&D units presently being delivered and in the future. You can identify this new data connection on your units by color, if green in color this new adapter is needed, if grey prior adapter is used. This new connector is included with the In-Line 7 Data Link.

**PART #5299126
CALL TODAY FOR
PRICING!**

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT OUR PARTS DEPARTMENT WITH ANY QUESTIONS

Director of Parts

Jim Hogan

jhogan@newyorkbussales.com

607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Dave Grant

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

John Green

jgreen@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

Ryan Krolak

rkrolak@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

