

GM MICROBIRD FLOOR BY CONSOLE

Tech Tip #16-0413





NO THERE IS NOT A FLAREBOX UNDER THE MAT

It has been brought to our attention that something is under the GM front floor mat, just behind the "Dog House" and to the right of the driver's seat. We checked, and found it is the "YAW" sensor for the Electronic Stability Control.

Normally on a GM "G" Series van, this sensor is located under the passenger seat. With that seat removed, it has been relocate to the current position.

NOTE: A yaw-rate sensor is a gyroscopic device that measures a vehicle's angular velocity around its vertical axis. The angle between the vehicle's heading and vehicle actual movement direction is the "slip angle", which is related to the yaw rate.

Thanks to Doug from Wheatland Chili Central School for pointing this out

ALL of our Service Updates can be found on the New York Bus Sales website or at the New York Head Mechanic website







CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232

Melinda LaDue

Albany: 866-867-1100

Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins

Customer Service Representatives

Eastern Region:

Gary Bigness 845-500-3707

Central Region:

JJ Richmond 315-59-3999

Western Region:

Mike Panzica 716-908-3186

PARTS

Jim Hogan 607-227-5794 jhogan@newyorkbussales.com

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com
Bill Cox bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com Dave Grant dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

John Green

jgreen@newyorkbussales.com

Rochester: 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

Ryan Krolak

rkrolak@newyorkbussales.com

ALL of our Service Updates can be found on the <u>New York Bus Sales website</u> or at the <u>New York Head Mechanic website</u>





