

## 14-0911-1 – Battery Stud

### Product Affected – Chassis Mounted Battery Box Stud

- Complaint:** When servicing the batteries, the power cable is “loose” where the cable goes through the back of the battery box.
- Cause:** There is a power stud mounted behind the battery box and with the battery tray moving in and out the pulling on the cable loosens the stud.
- Correction:** Figure #1 shows the stud mounted to the battery box and the spanner nut holding the stud to the box. Figure #2 shows the stud to the rear of the box. One thing we found is the spanner nut is located in such a position that it is difficult to get a spanner wrench or socket on it. If you disconnect the batteries, remove the cables and then remove the stud and re-install 180\* so that the spanner nut is located to the rear you can get a better “grip” on it with your spanner wrench or socket. Adding a drop of Loctite will help ensure the stud will not loosen from future movement of the cables. See figures #3 and #4-




Fig 1




Fig 2



**Fig 3**



**Fig 4**

**PLEASE NOTE - BLUE BIRD WILL BE CHANGING THE ORIENTATION OF THE  
STUD/SPANNER NUT IN PRODUCTION**

**THANKS TO YUKON AND BEN FROM THE RAVENA SHOP FOR POINTING THIS OUT**

**For more information contact our nearest Service Department or your Customer Service Representative**

**Chittenango: 315-687-3969 or 1-800-962-5768**

**Rochester: 585-424-3320 or 1-800-463-3232**

**Ravena: 518-756-1111 or 1-866-867-1111**

**Daryl Wallace or Brian Lamaitis**

**Gary Chichester or Dave Schaub**

**Ben Reiling**

**Customer Service Representatives**

**Eastern Region**

**Central Region**

**Western Region**

**Gary Bigness 845-500-3707**

**JJ Richmond 315-559-3999**

**Mike Panzica 716-908-3186**