



Tech Tip 16-0207-2

Stemco Wig-Wag Sticking

Complaint: the wig-wag does not drop when drivers pump down the brakes during their pre-trip routine. The flag was changed, operated properly and put back into service. The next cold morning it stuck again.

Cause: after the unit warms, the flag operates properly leading us to believe either cold temperatures, moisture in the air or possibly the contraction rate of different metals used caused the flag to hang up.

Correction: We are contacting Stemco; but recommend spraying lubricant such as WD40 on the pin area of the flag to disperse moisture.

For more information, contact our nearest Service Department

Chittenango: 315-687-3969 or 1-800-962-5768

Daryl Wallace or Brian Lamaitis

Rochester: 585-424-3320 or 1-800-463-3232

Dave Schaub

Ravena: 518-756-1111 or 1-866-867-1111

Ben Reiling

Customer Service Representatives

Eastern Region Gary Bigness 845-500-3707

Central Region JJ Richmond 315-559-3999

Western Region Mike Panzica 716-908-3186