

From your friends at New York Bus Sales

Product Effected - Blue Bird units with Air Brakes

The steel guard used to insulate the rear air lines from exhaust heat Complaint:

cause the exhaust pipes to prematurely rust thru.

Cause: These shields being down where all the road debris, slush, ice and

> those wonderful chemicals used on the road have cavities and voids where these items are held and cause the process of deterioration

to accelerate.

Correction: Blue Bird currently uses a sleeved "heat shield" which goes over

the air hoses to protect them from heat. These sleeves can be used

in lieu of the steel heat shield.

PLEASE NOTE - HEAT SLEEVE PART # 00118668



Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace: dwallace@newyorkbussales.com Brian Lamaitis: blamaitis@newyorkbussales.com **ROCHESTER** – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY - phone 866-867-1100 or

Ben Reiling: <u>breiling@newyorkbussales.com</u> Steve Searles: ssearles@newyorkbussales.com WARRANTY - 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at http://www.newyorkbussales.com/pages/bulletins.cfm Or at the New York Head Mechanic website at http://www.nyhma.org/viewforum.php?f=2&start=0

