

Tech Tip



From your friends at New York Bus Sales

Product Affected-Blue Bird's New D3 All-American and New Vision

- Complaint -** We just changed the dash cluster (BB #10012167) and we are getting an ABS light, ATC (Automatic Traction Control Light) and we cannot find an issue!
- Cause -** ALL New dashes are programmed with version 5.4 and if Recall #R10SH-2 (Cruise Control) has not been completed then these issues will occur-
- Correction -** Before changing the dash cluster (new style Actia shown in Figure #1) Make sure that the recall has been done currently we have the majority of these recalls done but if we have not gotten yours done and a dash needs to be changed we will schedule to come and do the recall so that you do not have any issues!



Figure #1



Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or
Daryl Wallace : dwallace@newyorkbussales.com
Brian Lamaitis : blamaitis@newyorkbussales.com
ROCHESTER – phone 800-463-3232 or
Gary Chichester: gchichester@newyorkbussales.com
ALBANY – phone 866-867-1100 or
Ben Reiling: breiling@newyorkbussales.com
Steve Searles: ssearles@newyorkbussales.com
WARRANTY – 800-962-5768 ext 237
Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at
<http://www.newyorkbussales.com/pages/bulletins.cfm>
Or at the New York Head Mechanic website at
<http://www.nyhma.org/viewforum.php?f=2&start=0>