

Tech Tip

FROM YOUR FRIENDS AT
NEW YORK BUS SALES!



Blue Bird Type C & D w/Air Ride – Exhaust Shield

- Complaint –** There is an air leak at the back of the unit
- Cause –** New York Bus Sales as an added protection to the rear air brake lines added an exhaust shield (Figure #1). The bracket will over time cut into the air brake hose causing a leak.
- Correction –** Remove the shield – The foil wrap installed by Blue Bird is more than sufficient protection for the hoses.




Figure #1



NEW YORK BUS SALES

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : dwallace@newyorkbussales.com

Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or

Ben Reiling: breiling@newyorkbussales.com

WARRANTY – 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at

<http://www.newyorkbussales.com/pages/bulletins.cfm>

Or at the New York Head Mechanic website at

<http://www.nvhma.org/viewforum.php?f=2&start=0>