

Tech Tip

FROM YOUR FRIENDS AT
NEW YORK BUS SALES!



BBCV & T3FE Air Brake Noise

- Complaint –** We are getting a brake “squeal” on our new unit(s)
- Cause –** We are currently working with Meritor and Blue Bird to resolve the issue!
- Correction –** New York Bus Sales has received phone calls concerning brake noise on units delivered this year.....NOT necessarily all units of a customer but seems to be only certain units and are currently working with the manufacturers to resolve the issue BUT the fix is not as easily resolved as we had hoped.

Should you have experience the issue we would recommend as a temporary repair that the brake shoes be “burnished” per the attached Blue Bird Service Update SU1107 to remove brake shoe glaze and seat the shoes with the drums. We realize that this is NOT a resolution but will help with the noise until a permanent resolution is found.

We appreciate your patience and help with this until we can get a resolution and implement it!

THANK YOU!



ALL of our Tech Tips can be found on the New York Bus Sales website at
<http://www.newyorkbussales.com/pages/bulletins.cfm>
Or at the New York Head Mechanic website at
<http://www.nyhma.org/viewforum.php?f=2&start=0>