

Tech Tip

FROM YOUR FRIENDS AT
NEW YORK BUS SALES!



Blue Bird BBCV-Vision

- Complaint –** With the inclement weather the lower glass of the entrance door becomes “coated” with grime and impairs the driver’s vision out the door.
- Cause –** Seeing as the right front tire is just ahead of the door, especially in a left turn, it is literally throwing the debris around and just pulling up slowly or pulling away with the door open causes the door to be “coated” with the debris.
- Correction –** New York Bus Sales has made a bracket and found a mudflap which when installed follows the contour of the fender and comes out further so as to keep road debris from being thrown down the side of the bus and more importantly on the entrance door.



FIGURE #1



FIGURE #2

Parts Required

		LIST
#NYB-047	BRACKET	\$40.40
#00076719	MUDFLAP	\$27.13



FIGURE #3

**ALSO AVAILABLE ON NEW
ORDERS**

OPTION #BDY141

Thank You to Pete Marini and the Techs
at Fairport Central School for bringing
this to our attention.



Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : dwallace@newyorkbussales.com

Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or

Ben Reiling: breiling@newyorkbussales.com

WARRANTY – 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

Or Your Customer Support Representative

West

Michael Panzica – mpanzica@newyorkbussales.com

Cell 716-908-3186

Central

Jeremie “JJ” Richmond –

jjrichmond@newyorkbussales.com

Cell 315-559-3999

East

Gary Bigness – gbigness@newyorkbussales.com

Cell 845-500-3707

ALL of our Tech Tips can be found on the New York Bus Sales website at

<http://www.newyorkbussales.com/pages/bulletins.cfm>

Or at the New York Head Mechanic website at

<http://www.nyhma.org/viewforum.php?f=2&start=0>