



Fault Code P009E With Propane Service Update #26-0721



CEL and Fault Code P009E – BOTH 6.8L & 7.3L

During our recent training at the NYHMA Summer Seminar in Syracuse, Fault Code P009E was discussed:

P009E – Fuel Pressure Relief Control Circuit

Fault code P009E indicates a performance issue or a "stuck off" state in the Fuel Pressure Relief Control circuit. This means the Powertrain Control Module (PCM) detected an electrical or mechanical fault where the fuel pressure relief valve or its regulating solenoid failed to actuate properly.

As it was discussed more in-depth, we learned that the system activates the bleed solenoid 45 minutes after "key off" to purge the vapor in the line.

When the now standard battery cutoff switch option is turned off immediately following the unit being used, it cuts off the power to the bleed solenoid which does not allow the vapor to be purged, and it can actually trigger the fault.

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT US FOR SERVICE or QUESTIONS

Director of Service

Matt Woodman

mwoodman@newyorkbussales.com

Chittenango: 800-962-5768

Morgan Jenkins

mjenkins@newyorkbussales.com

Brian Goodfellow

bgoodfellow@newyorkbussales.com

Bob Reith

breith@newyorkbussales.com

Phil Tucker

ptucker@newyorkbussales.com

Albany: 866-867-1100

Ross Phipps

rphipps@newyorkbussales.com

Customer Support

Ben Reiling

breiling@newyorkbussales.com

Batavia: 800-463-3232

Matt Dargusch

mdargusch@newyorkbussales.com

Eric Bosley

ebosley@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Road Mechanic website](#)

