

# NEXTGEN Child Restraint Seat Meets ALL FMVSS 213 Tech Tip #19-0316



# NEXTGEN SEATS DON'T LIMIT SEATING CAPACITY WHEN CHILD RESTRAINTS ARE REQUIRED

During a recent Transportation meeting, the discussion lead to the various harnesses and restraints required to transport some children. Many operations use the various brands of harness systems which attach to the standard school bus seat. The HSM version can be seen in Figure #1.

These systems must meet and are tested under FMVSS 213 and while performing their intended function, have limitations and in many cases require the seat directly behind not be occupied. (See Figure #2).

The question was asked if this was true on the school bus seats with the integrated restraint systems and we have verified that the NEXTGEN seat provided in the Blue Bird product is tested for and meets all FMVSS 213 standards without compromising child capacity.

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website









FIGURE #1 (HSM's Portable Child Restraint)

(b) Harnesses manufactured for use on school bus seats must meet S5.3.1(a) of this standard, unless a label that conforms in content to Figure 12 and to the requirements of S5.3.1(b)(1) through S5.3.1(b)(3) of this standard is permanently affixed to the part of the harness that attaches the system to a vehicle seat back. Harnesses that are not labeled as required by this paragraph must meet S5.3.1(a).

Artwork Gray and Black
With White Background

Circle and Line Red
With White Background

WARNING! This restraint must only be used on school bus seats. Entire seat directly behind must be unoccupied or have restrained occupants.

Label Outline, Vertical and Horizontal Line Black

Figure 12. Label on Harness Component That Attaches to School Bus Seat Back.

### FIGURE #2

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website







# CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

#### **SERVICE**

Chittenango: 800-962-5768
Daryl Wallace or Brian Lamaitis
Rochester: 800-463-3232

**Dave Schaub** 

Albany: 866-867-1100

Ben Reiling

**Lower Hudson Valley Region:** 

845-609-7070 Marc Matwijec

Warranty: 800-962-5768

Morgan Jenkins

Customer Service Representatives

#### **Eastern Region:**

Gary Bigness 845-500-3707

### **Central Region:**

Josh Coon 315-263-0765

## **Western Region:**

Mike Panzica 716-908-3186

#### **PARTS**

#### **Director of Parts**

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

**Chittenango:** 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

**Dave Grant** 

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

Rochester: 800-463-3232

**Tim Gross** 

tgross@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website





