## Blue Bird Vision Power Steering

Tech Tip #17-0323



## Fluid "foaming" at the reservoir and "seepage"

With older units, the power steering reservoir was mounted up on the fire wall on the driver's side. In colder weather this set up had some issues. The fluid could be seen "foaming" and coming out the vent of the cap. Seepage could also be seen at the ends of the return hose.

Working with Blue Bird, we found that there was an alternate hose which could be used and would address this issue. Units are built with both a ½" or ¾" hose. Please see the part numbers in Figure #1 for the proper replacement hose number.

Blue Bird has changed the location of the reservoir. It is now located just forward of the radiator on the left side between the frame rail. We have not seen any problems since these hoses went into production.

PLEASE NOTE – We recommend using "constant torque" clamps if replacing the hose. This is not a warrantable issue.

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website







Part #10041589 Hose, Low Pressure, .50 ID, Braid, Black EC00408

Part #10041590 Hose, Low Pressure, .75 ID, Braid, Black EC00412

Figure #1

ALL of our Service Updates can be found on the New York Bus Sales website
Or at the New York Head Mechanic website







## CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

**SERVICE** 

**Chittenango:** 800-962-5768 Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232

**Dave Schaub** 

Albany: 866-867-1100

Ben Reiling

Warranty: 800-962-5768

Morgan Jenkins
Customer Service
Representatives

**Eastern Region:** 

Gary Bigness 845-500-3707

**Central Region:** 

JJ Richmond 315-559-3999

**Western Region:** 

Mike Panzica 716-908-3186 **PARTS** 

**Director of Parts** 

Jim Hogan jhogan@newyorkbussales.com 607-227-5794

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Bill Cox

bcox@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

**Dave Grant** 

dgrant@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Pat Murphy

pmurphy@newyorkbussales.com

**Rochester:** 800-463-3232

Dave Cook

dcook@newyorkbussales.com

Steve Hibbard

shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the New York Bus Sales website

Or at the New York Head Mechanic website





