

From your friends at New York Bus Sales

## Product Effected -All American "D3"

Complaint: At highway speeds there is a "whistling" sound from the entrance door area.

This will only occur with all windows closed and you can verify by opening the

driver's window while the noise is there and seeing if it silences.

Cause: The increased size of the entrance door may allow the door to flex in the center

and allow air pressure to push through the original seal at the forward edge of the entrance door causing the "whistle" The original seal was a "lip" seal where this new seal is a "bulb" type and is made of a "softer" and slightly

wider material which flexes with the door movement assuring a better seal.

Correction: Replace the original seal with part number 10010610 – When installing the new seal we have found that using some adhesive along with assuring that the seal

is installed tightly along the entire length will greatly help as when not

installed properly the seal will come off due to the door operation.

PLEASE NOTE: We have seen the issue mainly with the D3 product but it can also be used if the A3 and BBCV exhibit the problem. This is a product improvement not covered by warranty.



## Contact Our Service Department With Any Questions

**CHITTENANGO** – phone 800-962-5768 or

Daryl Wallace: <a href="mailto:dwallace@newyorkbussales.com">dwallace@newyorkbussales.com</a>
Brian Lamaitis: <a href="mailto:blamaitis@newyorkbussales.com">blamaitis@newyorkbussales.com</a>

**ROCHESTER** – phone 800-463-3232 or

 $\textit{Gary Chichester:} \ \underline{\textit{gchichester}} \underline{\textit{@newyorkbussales.com}}$ 

**ALBANY** – phone 866-867-1100 or

Ben Reiling: <u>breiling@newyorkbussales.com</u>

Steve Searles: <a href="mailto:ssearles@newyorkbussales.com">ssearles@newyorkbussales.com</a>

WARRANTY - 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at

http://www.newyorkbussales.com/pages/bulletins.cfm
Or at the New York Head Mechanic website at
http://www.nyhma.org/viewforum.php?f=2&start=0