## SERVICE NOTICE NEW YORK BUS SALES

Recently we have learned some SBCV (International Conventional) units with 8,000 lb. axles and certain air brake options do not have dust shields on the front brakes.

## Those options are:

- Front Axle Option #0002AEM Dana Spicer D800-F 8,000# Front Axle
- Brake Option #0004JBM 15X5 Front S-CAM W/20" long stroke chambers

International engineering notified us of the possibility of finding dust shields through Spicer, but they were excluded because of heat buildup and are not recommended by International

Should you have questions or concerns, we recommend you contact your local International dealer.

CHITTENANGO - phone the Service Department at 800-962-5768 or email

Daryl Wallace: dwallace@newyorkbussales.com Brian Lamaitis: blamaitis@newyorkbussales.com

**ROCHESTER** - phone the Service Department at 800-463-3232 or email Gary Chichester: <a href="mailto:gchichester@newyorkbussales.com">gchichester@newyorkbussales.com</a>

**ALBANY** - phone the Service Department at 866-867-1100 or email

Steve Searles: <a href="mailto:ssearles@newyorkbussales.com">ssearles@newyorkbussales.com</a>
Ben Reiling: <a href="mailto:breiling@newyorkbussales.com">breiling@newyorkbussales.com</a>

THANK YOU