




Braun Interlock “Jumper”

Part #31797AKS to diagnose where lift issues lie



The Braun Interlock “Jumper”:

From the recent Braun Training in Horseheads this Interlock "Jumper" can be used to help you diagnose if an issue with a lift operation is with the lift itself or the vehicle the lift is installed on.

Purchase a Jumper Interlock:

Part #31797AKS

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT US WITH ANY QUESTIONS YOU HAVE!

SERVICE

Director of Service

Ryan Hemund
rhemund@newyorkbussales.com
CELL 315-561-9121

Chittenango: 800-962-5768

Brian Lamaitis
blamaitis@newyorkbussales.com
Bob Reith
breith@newyorkbussales.com
Phil Tucker
ptucker@newyorkbussales.com
Brian Goodfellow
bgoodfellow@newyorkbussales.com

Albany: 866-867-1100

Ben Reiling
breiling@newyorkbussales.com

Batavia: 800-463-3232

Keetah Wallace
kwallace@newyorkbussales.com

PARTS

Director of Parts

Matt Woodman
mwoodman@newyorkbussales.com
CELL 315-271-9748

Chittenango: 800-962-5768

Gari McQuade
gmcquade@newyorkbussales.com
Ted Nerveldine
tneveldine@newyorkbussales.com
John Lewin
jlewin@newyorkbussales.com
Garry Maniacek
gmaniacek@newyorkbussales.com
Jim Mattner
jmattner@newyorkbussales.com

Albany: 866-867-1100

Sean Conway
sconway@newyorkbussales.com
Dan Haight
dhaight@newyorkbussales.com

Batavia: 800-463-3232

James Roeser
jroeser@newyorkbussales.com
Tyler Hartigan
thartigan@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

