

Incorrect Label Placement Part #01966993

Parts Update #24-0930



FIGURE #1



FIGURE #2



FIGURE #3

Fuel/Water Separator Element Label Placement

We were just contacted concerning the possibility of an issue with the placement of the Blue Bird labeling tag and where it is located replacement filters available through Parts.

The filter comes in a zip-lock bag and the tag is located as shown in FIGURE #1. Once the filter is removed from the bag to be installed, we are asking that you make sure the tag as shown in FIGURE #2 is removed along with any adhesive residue and cleaned as in FIGURE #3.

PLEASE NOTE:

New York Bus Sales has removed tags from filters in stock and Blue Bird is working to address filters in their stock.

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT OUR PARTS DEPARTMENT WITH ANY QUESTIONS

Director of Parts

Matt Woodman

mwoodman@newyorkbussales.com

Cell 315-721-9748

Chittenango: 800-962-5768

Gari McQuade

gmcquade@newyorkbussales.com

Ted Neveldine

tneveldine@newyorkbussales.com

Garry Maniacek

gmaniacek@newyorkbussales.com

John Lewin

jlewin@newyorkbussales.com

Albany: 866-867-1100

Sean Conway

sconway@newyorkbussales.com

Dan Haight

dhaight@newyorkbussales.com

Batavia: 800-463-3232

James Roeser

jroeser@newyorkbussales.com

Tyler Hartigan

thartigan@newyorkbussales.com

Outside Parts Sales

Sales Manager

Steve Quintal

squintal@newyorkbussales.com

Cell 315-236-3203

East

Chad Dumar

cdumar@newyorkbussales.com

Cell 845-500-3707

Central

Mike Rubino

mrubino@newyorkbussales.com

West

Rich Mently

rmently@newyorkbussales.com

Southwest

Heather Knopp

hknopp@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)



©2015 New York Bus Sales. All rights reserved.

Comments or Concerns:

John Johnston
jjohnston@newyorkbussales.com
Cell 315-263-0766